epoc
BLOOD ANALYSIS

Enabling the New Parameters

- To login in to Admin mode fill in the login fields as below
  Username: administrator
  Password: administrator

- Choose Tools > Options > Card options 1

- Choose the second tab as below

- Enable and select the below parameters as required
  TCO2 (now measured rather than calculated)
  BUN
  Urea
  BUN/Crea
  Urea/Crea

- Press the save icon and ok to confirm

- Press the red x to close the options screen and Tools > Logout > Yes.

Tel: +44 (0)1204 669033
Fax: +44 (0)1204 669034
Email: sales@woodleyequipment.com
Web www.woodleyequipment.com

WOODLEY
EQUIPMENT COMPANY LTD.

OLD STATION PARK BUILDINGS . ST. JOHNS STREET . HORWICH . BOLTON . LANCASHIRE . BL6 7NY